



















名 称	形 状	径	切寸	本数	箇所	合計	定尺	割	本数	圧接
1階段②										
2 2/23 8:15		SD295	D10 2250			8	4500	2	4	
3		SD295	D10 1300			7	4000	3	3	
4		SD295	D10 1500			7	4500	3	3	
5		SD295	D10 1550			12	5000	3	4	
6		SD295	D10 2250			2	4500	2	1	
7		SD295	D10 1100			7	5500	5	2	
8		SD295	D10 1550			4	5000	3	2	
9		SD295	D10 1600			6	5000	3	2	
10		SD295	D10 1600			20	5000	3	7	
11		SD295	D10 1730			7	3500	2	4	
12		SD295	D10 1800			12	5500	3	4	
13		SD295	D10 2750			5	5500	2	3	
14		SD295	D10 3150			6	6500	2	3	
15		SD295	D10 4850			7	5000	1	7	
16		SD295	D10 2800			5	6000	2	3	
17		SD295	D10 1530			5	5000	3	2	
18		SD295	D10 3350			7	3500	1	7	
19		SD295	D10 1770			5	5500	3	2	
20		SD295	D10 1150			5	3500	3	2	

	名 称	形 状	径	切寸	本数	箇所	合計	定尺	割	本数	圧接
21	階段②		SD295	D10	4000		11	4000	1	11	
22											
23			SD295	D13	1300		4	4000	3	2	
24			SD295	D13	2250		20	4500	2	10	
25			SD295	D13	1000		3	5000	5	1	
26			SD295	D13	1300		5	4000	3	2	
27			SD295	D13	1380		14	4500	3	5	
28			SD295	D13	1500		7	4500	3	3	
29			SD295	D13	1550		4	5000	3	2	
30			SD295	D13	1600		14	5000	3	5	
31			SD295	D13	1750		7	3500	2	4	
32			SD295	D13	1750		2	3500	2	1	
33			SD295	D13	1950		16	4000	2	8	
34			SD295	D13	1950		9	4000	2	5	
35			SD295	D13	2250		2	4500	2	1	
36			SD295	D13	1200		14	6000	5	3	
37			SD295	D13	1650		4	5000	3	2	
38			SD295	D13	1700		2	3500	2	1	
39			SD295	D13	1830		6	5500	3	2	
40			SD295	D13	1200		23	6000	5	5	

[illegible]

(上部分)

[illegible]